

Formula for “black mark” removal (low-e glass)

Preparation

- This is a mild acidic solution. Standard precautions on working with acids apply, i.e. use of gloves, good ventilation and face masks, especially for persons with respiratory issues.
- Protect floor surfaces
- Avoid spillage and dripping on stone surfaces. Remember: acids will attack most mineral materials

Formula

- Pour 20-30ml of hydrochloric acid (pool acid) Preparation:
- into a 1 litre spray bottle.
- Fill the bottle up with 1 litre of clean water
- It is imperative to pour water into the acid and not the other way round

Application

- Spray small amounts on to the damaged area
- Rub the area vigorously until the black marks disappear
- You may have to repeat the process more than once

Disclaimer

This solution will not remove scratches that have penetrated the low-e coating